



8/23/2022 12:29

### Work Order # 6145428

*Activity Code* A40010  
*Activity Description* PATCH POT HOLES FLEX PAVEMENT  
*Asset* Roadway  
*Asset ID* 07-LA-101  
*From* 9.220  
*From Unit Of Measure* PM(PM)  
*To* 16.940  
*To Unit Of Measure* PM(PM)  
*Feature Type* Element  
*Feature Code*  
*Feature Value*  
*Asset Description*

### Summary

Closed on 6/14/2022 by EDDIE WALKER.  
 SCRT Priority.  
 Maintenance Type is SAFE.  
 Budget is 0000000011-N-036.

### Information

#### Work Order Information

*Initiated* 2/19/2022 00:00  
*Initiated By* 139602  
*Assigned To* 139602  
*Responsibility* 071991  
*Budget Number* 0000000011-N-036  
*Reporting Code*  
*Maintenance Type* SAFE  
*Problem*  
*Priority* SCRT  
*Project*  
*Region* 071967  
*Area* 071978  
*Group Project*  
*Service Request*  
*Incident*  
*Reference #*

*Work Completed* 6/14/2022 08:29  
*Completed By* 139602  
*Actual Quantity* 7.000  
*Unit of Measure* EA  
*Usage* 0.0000  
*Closed* 6/14/2022 08:29  
*Cancel Work Order* no  
*Approval Date*  
*Approved By*

### Attachments

#### Attachments

(No Data)

### Resource Usage

Delete Selected Usage

#### Resource Usage

Activity Task	Usage Type	Item	Description	Usage	Units	Rate	Total Cost	Charge From	Charge To	Comments
A40010	Labor	6297	CASH OT DAY SHIFT PLANNED	8	Hours	23.8274	285.9288	2/19/2022	2/19/2022	02/19/2022:

		(149642)					02:00	10:00	EMPLOYEES WERE REPAIRING MULTIPLE "CSR" POT HOLES.#1592857, 1591189, 1554191, 1620552.
A40010	Labor	6297 (142981)	CASH OT DAY SHIFT PLANNED	8	Hours	24.6351 295.6212	2/19/2022 02:00	2/19/2022 10:00	02/19/2022: EMPLOYEES WERE REPAIRING MULTIPLE "CSR" POT HOLES.#1592857, 1591189, 1554191, 1620552.
A40010	Labor	6301 (139602)	CASH OT DAY SHIFT PLANNED	8	Hours	35.6141 427.3692	2/19/2022 02:00	2/19/2022 10:00	02/19/2022: EMPLOYEES WERE REPAIRING MULTIPLE "CSR" POT HOLES.#1592857, 1591189, 1554191, 1620552.
A40010	Vehicle	7012183	CARGO BODY 12FT CREW CAB W/HOIST CARGO BODY 12' CREW CAB GAS	8	HR	12.32 98.56	2/19/2022 02:00	2/19/2022 10:00	
A40010	Vehicle	9000830	UTILITY BODY 3/4 TON RENTAL UTILITY BODY 3/4 TON	8	HR	20.8 166.4	2/19/2022 02:00	2/19/2022 10:00	
A40010	Vehicle	7009715	UTILITY BODY 1 TON UTILITY BODY	8	HR	22.85 182.8	2/19/2022 02:00	2/19/2022 10:00	

**Comments**

**Comments**

02/19/2022: EMPLOYEES WERE REPAIRING MULTIPLE "CSR" POT HOLES.#1592857, 1591189, 1554191, 1620552.

**Planned Tasks**

(Tab Not Loaded)

**Cost Summary**

(Tab Not Loaded)

**Roadway History**

(Tab Not Loaded)

**Chemical Usage Details**

**Chemical Usage**

**Chemical Usage**

(No Data)

**Pesticide Use Recommendation**

Number 0  
 Applicator # 0  
 Expire Date  
 Completed no

**PPE Details**

**PPE Details**

(No Data)

**Production Units and Support**

**Production Units and Support**

**Production Units**

Primary Production Unit :  
 EACH  
 Secondary Production Unit:

Element

**Production Units**

Work Date Production Units Unit Of Measure Secondary Units Secondary Unit of Measure

2/19/2022 7 EA 0

### Support Activities

Work Date	Travel (Person Miles)	Travel (Person Hours)	Delays ( Each Occurrence)	Delays ( Person Hours)	Traffic Control Hours	Equip Prep Hours	Assist Mech Hours	Service Equip Hours	Transport Equip Mtce Hours	Transport Equip Shop Hours	Comments
2/19/2022	15	0.2727	0	0	5	1.5	0	0	0	0	

### Reportable Items

(No Data)